R-585-12-9-29

SITE INSPECTION USING AVAILABLE INFORMATION OF ROCKWOOD COMPRESSOR STATION PREPARED UNDER

TDD NO. F3-8910-16 EPA NO. PA-2165 CONTRACT NO. 68-01-7346

FOR THE

HAZARDOUS SITE CONTROL DIVISION
U.S. ENVIRONMENTAL PROTECTION AGENCY

APRIL 5, 1990

NUS CORPORATION SUPERFUND DIVISION

SUBMITTED BY

PROJECT MANAGER

REVIEWED BY

SECTION SUPERVISOR

REGIONAL MANAGER, FIT 3

Site Name: Rockwood Compressor Station
TDD No.: F3-8910-16

(ii. s)

TABLE OF CONTENTS

SECTION	<u>P</u>	AGE
1.0	INTRODUCTION	1-1
1.1	AUTHORIZATION	1-1
1.2	SCOPE OF WORK	1-1
1.3	SUMMARY	1-1
2.0	THE SITE	2-1
2.1	LOCATION	2-1
2.2	SITE LAYOUT	2-1
2.3	OWNERSHIP HISTORY	2-4
2.4	SITE USE HISTORY	
2.5	PERMIT AND REGULATORY ACTION HISTORY	2-5
2.6	REMEDIAL ACTION TO DATE	2-7
3.0	ENVIRONMENTAL SETTING	
3.1	WATER SUPPLY	3-1
3.2	SURFACE WATERS	3-2
3.3	HYDROGEOLOGY	
3.3.1	GEOLOGY	3-2
3.3.2	SOILS	3-5
3.3.3	GROUNDWATER	3-7
3.4	CLIMATE AND METEOROLOGY	3-9
3.5	LAND USE	3-9
3.6	POPULATION DISTRIBUTION	3-9
3.7	CRITICAL ENVIRONMENTS	3-9
4.0	WASTE TYPES AND QUANTITIES	4-1
5.0	EPA SITE INSPECTION FORM	5-1
6.0	REFERENCES FOR SECTIONS 1.0 THROUGH 5.0	6-1

TDD No.: F3-8910-16

APPENDICES

A 1.0 ROY F. WESTON PIT CLEAN-UP PROGRAM
FOR THE PENNSYLVANIA SITES, JANUARY 28, 1988

B 1.0 DETAILED PLAN FOR INVESTIGATION AND
CHARACTERIZATION OF IDENTIFIED AREAS AT
TEXAS EASTERN'S PENNSYLVANIA SITES

C 1.0 ROY F. WESTON REVIEW AND EVALUATION
OF PHASE I GROUNDWATER MONITORING AND
ASSESSMENT PROGRAM

PLATES

1. FOUR-MILE-RADIUS MAP

SECTION 1

TDD No.: F3-8910-16

1.0 INTRODUCTION

1.1 <u>Authorization</u>

NUS Corporation performed this work under Environmental Protection Agency Contract No.

68-01-7346. This specific report was prepared in accordance with Technical Directive Document No.

F3-8910-16 for the Rockwood Compressor Station site, located in Black Township, Somerset County,

Pennsylvania.

1.2 Scope of Work

NUS FIT 3 was tasked to conduct a site inspection using available information of the subject site.

1.3 Summary

The Rockwood Compressor Station (22A) is owned by the Texas Eastern Gas Pipeline Company and is

located on its southern Pennsylvania pipeline. The southern pipeline was originally used by the

United States government during World War II for the War Emergency Pipeline. The government

used Rockwood as a pump station for crude oil and other petroleum products. Texas Eastern

purchased the pipeline from the government in the late 1940s. The station site has reportedly never

been used by Texas Eastern as a compressor station and is currently used for equipment storage and

as headquarters for gauging crews.

Routine operation and maintenance of a natural gas pipeline require the removal of liquids from the

pipeline system. The pipeline liquids are accumulated condensation that occurs as a result of

temperature and pressure reductions along the pipeline. These liquids consist of naturally occurring,

relatively low molecular weight hydrocarbons. Removal of these liquids occurs at compressor stations

along the pipeline, and disposal has traditionally been in unlined earthen pits on site. The use of the

disposal pits by the United States government during operation of the War Emergency Pipeline is

unknown.

Although there is a backfilled pit on site at the Rockwood station, Texas Eastern claims to have never

disposed pipeline liquids into the pit. Apparently, the pit was constructed by the government, but

the government's use of the pit is unknown. The pit is reported to have been closed by 1960.

1-1

TDD No.: F3-8910-16

In 1981, Texas Eastern discovered polychlorinated biphenyl (PCB) residues in the pipeline liquids. This source of PCB is attributed to the use of PCB lubricating oil from 1958 until 1977, which contaminated non-PCB lubricating oil used to replace the PCB oils. Apparently, the PCBs escaped the compressor seals and mixed with other condensate liquids. Texas Eastern attempted to remove the PCBs from the system by running solvents such as methanol and diesel fuel through the pipeline as cleaning agents.

Roy F. Weston, Incorporated was retained by Texas Eastern in 1985 to conduct a pilot study of potential contamination at eight compressor station sites along the pipeline. This study revealed the presence of PCBs at various locations, including soil and waters, of the preliminary assessment sites. Some of the materials listed on EPA's Hazardous Substances List (HSL), including volatile organic compounds, were discovered at these locations.

On April 1, 1987, a Consent Order was signed between the Pennsylvania Department of Environmental Resources (PA DER) and Texas Eastern. This Consent Order provided for source control modification, groundwater assessment and monitoring plans, additional pits and disposal areas, soil, stream sediment, and surface water assessment, clean-up plans, etc.

In compliance with the Consent Order, Texas Eastern installed three groundwater monitoring wells at Rockwood in October 1987. Subsequent sampling and analysis by Weston and PA DER revealed no detectable groundwater, surface water, or on-site surface soil contamination at the Rockwood Station.

PCBs were detected in some off-site soil and stream sediment samples, as well as in soil borings inside and outside the pit boundaries. Also identified in the inside boring sample analysis were 2-butanone, styrene, 2-methylnaphthalene, and naphthalene.

Residents within a three-mile radius of the site use groundwater and surface water as their potable water source. Those residents using groundwater do not have an alternate source of potable water available. The surface water sources for the two municipal systems serving parts of the study area are beyond the three-mile radius of the site.

TDD No.: <u>F3-8910-16</u>

2.0 THE SITE

2.1 <u>Location</u>

The Rockwood Compressor Station site is located approximately 1.3 miles south of the town of

Murdock and approximately 0.8 mile east of Coxes Creek (see figure 2.1, page 2-2). The grid

coordinates are 39° 56′ 18″ north latitude and 79° 06′ 12″ west longitude or 3.125 inches east and 11.5

inches north of the southwestern corner of the Murdock, Pennsylvania 7.5 minute series, United

States Geologic Survey (U.S.G.S.) quadrangle map.¹

2.2 Site Layout

The Rockwood Compressor Station encompasses approximately 19 acres and is fenced with a locked

gate (see figure 2.2, page 2-3).² One 20-inch and one 24-inch pipeline run through the property from

west to east.³ Texas Eastern occupies office, storage, and maintenance facilities, located centrally on

site, which were formerly the product station and crude station buildings used by the United States

government during the operation of the War Emergency Pipeline.4

A backfilled earthen disposal pit (PA-22-01) is located in the southeastern corner of the station site,

approximately 300 feet southeast of the office building. The pit is approximately 30 feet in diameter,

and the depth may be from 4 to 8 feet (see appendix A). A former crushed PCB drum storage area and

the former "pig" sending and receiving area are southwest and northwest of the office,

respectively.4,5

A dismantled 55,000-barrel fuel storage tank was located approximately 500 feet southwest of the

pit. Numerous concrete pads of dismantled station facilities remain throughout the site.3


Surface runoff from the southern part of the site is received by a spring-fed drainage ditch that

originates on site. This ditch combines with a roadside drainage ditch on the site's eastern border and

receives runoff from the northern part of the site. The roadside ditch combines with an unnamed

perennial tributary to Wilson Creek.1

2-1




SOURCE: (7.5 MINUTE SERIES) U.S.G.S. MURDOCK, PA., QUAD.

SITE LOCATION MAP ROCKWOOD COMPRESSOR STATION

SCALE 1: 24000





SITE SKETCH
ROCKWOOD COMPRESSOR STATION

(NO SCALE)

FIGURE 2.2



TDD No.: F3-8910-16

2.3 Ownership History

The Rockwood Compressor Station and the southern Pennsylvania pipeline are owned by Texas Eastern Transmission Corporation and its division, Texas Eastern Gas Pipeline Company. Texas Eastern

purchased the pipeline and the compressor station from the United States government in the late

1940s.^{4,6,7} Ownership prior to this time is unknown.

2.4 Site Use History

The Rockwood Compressor Station was used by the United States Government as a pump and storage

facility for crude oil and other petroleum products during World War II, as part of the War Emergency

Pipeline.^{4,6} A backfilled earthen disposal pit (PA-22-01) is located in the southeastern corner of the

station site.⁴ Although the pit is reported to have been last used by the government in the late 1940s,

the government's actual use of the pit is unknown. 7,8,9

In 1958, Texas Eastern began using Turbinol 153, a PCB lubricating oil produced by Monsanto, in its

compressors. By 1970, Turbinol 153 was used in 24 pipeline compressors at 19 locations in 8 states.

Monsanto ceased production of Turbinol 153 in 1972. Texas Eastern began phasing out its use of the

PCB lubricating oil in April 1972 and had completely eliminated its use of the oil by 1977.¹⁰ However,

residual PCB oil remaining in the compressor units contaminated the non-PCB replacement oil.^{10,11} In

1981, Texas Eastern also discovered PCBs in the pipeline liquids, which are routinely removed from the

system at the compressor stations. Apparently, PCB oil had seeped past the compressor seals and

mixed with other pipeline liquids. 10,12

In the past, as part of its operation of the compressor stations, Texas Eastern constructed earthen pits

for collecting pipeline liquids drained from gas/liquid separators and incoming "pig" runs.5,10

Pipeline pigs are used to remove accumulated pipeline liquids and solids from the gas pipeline. Using

pipeline pressure, pigs push the accumulated materials into a receiver or trap. The receiver is then

isolated from the pipeline and depressurized, and the gas and liquids are routed to a pig receiver

separator system, which will separate solids, liquids, and gases from each other. 12 The pits were also

used for disposal of the used lubricating oils collected from external drips or seeps from compressors

and used oils from other site operations. Liquid-handling facilities that were later constructed at the

compressor stations eliminated the need for the pits. Some pits were also used to train personnel in

fire-fighting techniques.5

2-4

TDD No.: <u>F3-8910-16</u>

Texas Eastern representatives report that the company currently uses Rockwood as a field station for gauging crews and has never used Rockwood as a compressor facility and that PCB oils and PCB-contaminated pipeline liquids were never disposed at the site by Texas Eastern.^{6,9}

2.5 Permit and Regulatory Action History

No permits are known to have been issued to Texas Eastern by PA DER for the treatment, storage, transportation, processing, discharge, or disposal of solids, industrial, or hazardous wastes.¹²

The Toxic Substances Control Act (TSCA) of 1976 specifically bans the manufacture, processing, distribution, and use of PCBs and regulates their disposal. Within TSCA, EPA developed the first PCB Rule in 1978 (superceded by the Final PCB Ban Rule, effective July 1979). Texas Eastern responded to the PCB Rule by breaking down and cleaning the 24 compressors that used the PCB oil and by only using compressor oils that did not contain PCBs. Over time, however, PCB levels rose over the 50 ppm level as the new oil became contaminated by PCB oil residue. In March 1979, only 7 compressors showed PCB levels over 50 ppm; however, by January 1980, the majority of the 24 compressors had PCB levels above 50 ppm. In July 1981, after repeating the cleaning operation, Texas Eastern's sampling program showed that PCB levels at all 24 compressors were below the required 50 ppm. However, in July 1982, the PCB concentration had again risen above 50 ppm at 16 of the compressors, and EPA issued a complaint against Texas Eastern. A penalty of \$159,800.00 was assessed to Texas Eastern. The penalty was later rescinded under an agreement with EPA because of Texas Eastern's good-faith effort to eliminate the PCBs. 10.13

In addition to the compressor-oil contamination, in January 1981, Texas Eastern discovered PCB in the pipeline liquids.¹³ Texas Eastern sampled 36 sites in March 1981 and filed a report of its results with EPA. In January 1982, EPA approved a pipeline liquids monitoring plan submitted by Texas Eastern, and the company began submitting quarterly reports of its sampling results.¹³

In August 1985, Texas Eastern informed EPA that it had discovered that condensates and waste oils had been disposed into earthen pits located on the compressor station sites. In response to EPA's request for further information, Texas Eastern retained the consulting services of Roy F. Weston, Incorporated to develop and conduct a detailed sampling program for the pit sites. Weston performed an initial Phase I pilot sampling program at eight compressor stations and, in April 1986, submitted a report to EPA entitled "Compressor Station Disposal Pit Investigation." The eight stations represented an operational and geological cross-section of Texas Eastern's system. 10,13,14

TDD No.: F3-8910-16

In June 1986, based on the results of the Phase I sampling program, Weston initiated the Phase II Eight Pilot Sites Sampling Program to fill in data gaps from Phase I and a 54-Site Screening Program to identify other sites containing earthen pits that may have been exposed to PCBs. The Rockwood Station was part of this 54-site screening. Results from Rockwood showed low PCB levels in the on-site disposal pit, low ppb levels of PCBs in on-site soil and sediments, and no PCBs in surface water and groundwater samples. As part of the sampling at the Phase II Eight Pilot Sites Sampling Program, data were collected to determine the potential presence of compounds on the HSL. As a result of these additional data, in January 1987, Weston prepared a memorandum summarizing the sampling and analysis for dioxin. There were no positive results reported for dioxin at the Rockwood Station. 14,15

On February 3, 1987, EPA's Office of Enforcement and Compliance Monitoring (OECM) advised Texas Eastern that site testing must address RCRA and Superfund contaminants and their cleanup. 10

PA DER began to conduct preliminary investigations on February 26, 1987 by sampling wells, soils, sediments, streams, fish, livestock, and milk from the areas immediately adjacent to and downgradient from the compressor station sites to determine the extent of contamination.¹⁰ The analysis results of PA DER's samples indicated no contamination at the Rockwood Station.^{3,6}

On April 1, 1987, Texas Eastern entered into a Consent Order and Agreement with PA DER (see appendix B).^{5,7,8} This Consent Order established a comprehensive phased program to assess environmental conditions at and around the 18 station sites along Texas Eastern's pipeline in Pennsylvania. The Consent Order also required a comprehensive clean-up plan for the pits. On January 28, 1988, Texas Eastern submitted a pit clean-up program for the Pennsylvania sites (see appendix A).^{5,10}

In January 1988, PA DER served Texas Eastern with an Assessment of Civil Penalties for seven counts of violations of the Solid Waste Management Act; fines totaled \$14,697,945.00.¹⁶ At this time, Texas Eastern and PA DER entered into a landmark agreement providing for payment of an amount up to \$1,000,000.00 to PA DER for the first year of oversight costs.¹⁰

TDD No.: F3-8910-16

On March 15, 1988, PA DER issued Texas Eastern a Unilateral Administrative Order, which required Texas Eastern to investigate, characterize, and remediate any additional pits and/or other areas identified by Texas Eastern that were not specifically addressed in the April 1, 1987 Consent Order. The order also obligated Texas Eastern to submit to PA DER, by May 16, 1988, detailed plans for the

investigation and characterization of these additional areas (see appendix B).8

Analysis from the Consent Order Phase I surface soil and sediment sampling at Rockwood Compressor Station did not reveal any PCBs in the on-site surface samples. Concentrations of 1.4 and 1.8 ppm were detected in two off-site surface samples, and concentrations of 38.0 and 24.0 ppm were detected in two stream sediment samples.¹⁷ Phase I groundwater sample analysis showed no detectable PCB concentrations.¹⁸ Three soil borings were also performed, one outside the identified pit and two inside the pit. In the outside boring, total PCBs were found at 2 and 2.1 ppm. The inside boring values were 10 to 24 ppm total PCBs. Also revealed in the inside boring were butanone (12 ppm), styrene (1.7 ppm), 2-methylnaphthalene (3.8 ppm), and naphthalene (6 ppm). From the boring descriptions, soil material and some waste residue were encountered; however, no oil waste was found.¹⁹

The Consent Order Phase II surface and sediment sampling was conducted at Rockwood by Weston on April 13, 1989. No PCBs were detected in on-site and off-site surface soil samples. Sediment samples did show a total PCB concentration of 1 to 6.4 ppm.²⁰ According to the Consent Order, it was not necessary to implement a Phase II groundwater monitoring plan, because PCBs and/or other HSL compounds were not detected in the Phase I sample analysis (see appendix C).⁹

Sampling for additional areas was conducted concurrently with Phase II sampling and showed no detectable PCB concentrations.8

2.6 Remedial Action to Date

The Rockwood Compressor site has never been used by Texas Eastern as a compressor station; Texas Eastern claims to have never disposed PCB contaminants in the on-site pit.⁶ The use of the pit during the site's operation as part of the United States government War Emergency Pipeline are unknown (see appendix C). The pit was closed in 1960; however, no remedial action has been performed at the site (see appendix C).⁹

2-7

SECTION 3

3.2 Surface Waters

An unnamed intermittent stream approximately 2,000 feet south-southeast the site is the nearest surface water. This stream flows approximately 5,000 feet in a southward direction to Wilson Creek, a perennial stream. Wilson Creek is between the one- and two-mile radii from the site. Wilson Creek flows approximately 2.5 miles to the west, where it joins with Coxes Creek, approximately four stream miles from the site, between the two- and three-mile radii. Coxes Creek flows to the south approximately 1.1 miles to its confluence with the Casselman River at the town of Rockwood, approximately 5.1 miles from the site, outside the three-mile radius.1

3.3 Hydrogeology

The geologic and hydrogeologic conditions in the study area were researched as part of the site inspection. A preliminary literature review was conducted to determine surface and subsurface geologic conditions, soil character, and the status of groundwater transport and storage.

3.3.1 Geology

The Rockwood Compressor site lies within the Allegheny Mountain Section of the Appalachian Plateaus Physiographic Province. The topography of the area is characterized by a series of parallel, northeast-trending ridges. Well-dissected areas, with a relief of approximately 500 feet occur between the ridges. The drainage pattern is dendritic, and the study area is drained by the Casselman River.1,17,22

TDD No.: F3-8910-16

Several wells and springs are located on or in proximity to the site. An on-site well exists next to the office and maintenance building, approximately 100 feet west and upgradient of the disposal pit. An off-site drilled well exists approximately 750 feet northwest and upgradient from the disposal pit. An off-site spring is located approximately 150 feet southeast and downslope from the disposal pit. Another spring is located approximately 500 feet west and upslope of the disposal pit. 9,28

3.2 Surface Waters

An unnamed intermittent stream approximately 2,000 feet south-southeast the site is the nearest surface water. This stream flows approximately 5,000 feet in a southward direction to approximately 5,000 feet in a southward direction to approximately 2.5 miles to the west, where it joins with approximately four stream miles from the site, between the two- and three-mile radii. So the south approximately 1.1 miles to its confluence with the confluence at the town of Responsible 1.1 miles from the site, outside the three-mile radius.

3.3 <u>Hydrogeology</u>

The geologic and hydrogeologic conditions in the study area were researched as part of the site inspection. A preliminary literature review was conducted to determine surface and subsurface geologic conditions, soil character, and the status of groundwater transport and storage.

3.3.1 Geology

The Line lies within the lies within the lies of the Appalachian Plateaus Physiographic Province. The topography of the area is characterized by a series of parallel, northeast-trending ridges. Well-dissected areas, with a relief of approximately 500 feet occur between the ridges. The drainage pattern is dendritic, and the study area is drained by the case. River, 1,17,22

TDD No.: <u>F3-8910-16</u>

The study area is underlain by a thick sequence of Mississippian and Pennsylvanian age sedimentary rocks. Compressional forces have folded these rocks into a series of northeast-southwest-trending, low-amplitude synclines and anticlines. The site is located on the western flank of the Negro Mountain anticline. The bedrock layers beneath the site dip gently to the northwest.^{24,29}

The uppermost bedrock unit underlying the western part of the site is the Pennsylvanian age Glenshaw Formation (see figure 3.1, page 3-4). The Glenshaw is the lowermost formation of the Conemaugh Group. It consists of alternating layers of shale, sandstone, limestone, minor coals, and clay. Marine limestones and shales are abundant, and some red beds are present. The Glenshaw Formation averages approximately 375 feet in thickness. At the site, only about 0 to 40 feet of the lower portion of the Glenshaw is present due to erosion of the upper layers.²⁴

The uppermost bedrock unit underlying the eastern part of the site is the Pennsylvanian age Freeport Formation (see figure 3.1, page 3-4). The Freeport is the uppermost formation of the Allegheny Group and stratigraphically underlies the Glenshaw Formation. It consists of alternating layers of shale, sandstone, coal, clay, and minor limestone. Shale, siltstone, and sandstone are the predominant lithology. The sandstones are massive and conglomeratic in places. The Freeport Formation averages approximately 100 feet in thickness.²⁴

Stratigraphically underlying the Freeport Formation, and cropping out just east of the site, is the Kittanning Formation of the Pennsylvanian age Allegheny Group. It consists of alternating layers of sandstone, shale, coal, clay, and minor limestone. Several of the coal beds show considerable variations, and some of the sandstone beds have irregular areal distributions. The Kittanning Formation averages about 100 feet in thickness.²⁴

Stratigraphically underlying the Kittanning Formation is the Clarion Formation of the Allegheny Group. It crops out within one mile northwest and southeast of the site. This formation also consists of alternating layers of sandstone, shale, coal, and clay. The Clarion Formation is approximately 75 feet thick.²⁴




FIGURE 3.1

GEOLOGIC MAP

Rockwood Compressor Site Somerset County, PA.



TDD No.: F3-8910-16

Stratigraphically underlying the Clarion Formation is the Pennsylvanian age Pottsville Group. It crops out within 1.5 miles southeast of the site. It consists of alterations of shale, major sandstones, and minor coal and clay. The coal beds are irregular both in thickness and in structure. Sandstones are sometimes thick bedded, massive, and locally conglomeratic. They range from coarse grained to fine grained and may grade laterally into siltstone and shale. The thickness of the Pottsville Group is usually about 200 feet.²⁴

Stratigraphically underlying the Pottsville Group Formation is the Mississippian age Mauch Chunk Formation. It crops out in the Casselman River valley in the southernmost part of the study area. It is composed of red, green, and gray shales and gray sandstones, with some marine limestones. The Mauch Chunk Formation varies greatly in thickness but is probably on the order of 500 feet thick in the study area.²⁴

3.3.2 Soils

Three native soil types are mapped as underlying the site (see figure 3.2, page 3-6). They are the Rayne-Gilpin channery silt loam (RgB, RgC), the Wharton silt loam (WhB), and the Cavode silt loam (CaB). The native soils of some areas of the site have been disturbed by construction and excavation.^{20,28,30}

The Rayne-Gilpin channery silt loam covers about 60 percent of the site. It is a deep and moderately deep well-drained soil formed in materials weathered from shale and siltstone. This unit consists of approximately 50 percent Rayne soils, 30 percent Gilpin soils, and 20 percent other soils. Rayne soils have a surface layer of very dark grayish-brown channery silt loam about eight inches thick. The subsoil is yellowish-brown channery silty clay loam and strong brown channery silty clay loam. The substratum is also strong brown channery silty clay loam. Bedrock is at a depth of about 55 inches and consists of weathered shale with interbedded siltstone and sandstone. Gilpin soils have a surface layer of dark brown channery silt loam about six inches thick. The subsoil is brown and yellowish-brown channery silt loam. Brown shale bedrock is at a depth of about 24 inches. The Rayne-Gilpin channery silt loams have moderate permeability (0.6 to two inches per hour) and are very strongly to strongly acid (pH 4.5 to 5.5).³⁰

The Cavode silt loam covers approximately 10 percent of the site. It is a deep, somewhat poorly drained soil formed in material derived from acid-brown shale and siltstone.

3-5




FIGURE 3.2

SOILS MAP

Rockwood Compressor Site Somerset County, Pa.



TDD No.: F3-8910-16

The surface layer is dark grayish-brown silt loam about eight inches thick. The subsoil is yellowish-brown silty clay loam; mottled gray silty clay; and mottled, light brownish-gray silty clay loam. The substratum is dark yellowish-brown silty clay loam. The permeability is moderate in the surface layer (0.6 to two inches per hour) and slow in the subsoil and substratum (0.06 to 0.2 inch per hour). This soil is very strongly to strongly acid (pH 4.5 to 5.5).³⁰

3.3.3 Groundwater

Groundwater in the study area occurs under both water-table and artesian conditions. Water is stored in both primary intergranular openings and in secondary openings such as fractures, joints, and solution openings. The primary avenue of groundwater movement is through the secondary openings, mainly through joints and fractures. Recharge of groundwater is from the infiltration of local precipitation downward through soils and rock to the zone of saturation. Groundwater generally moves downward and laterally from higher elevations and areas of recharge to lower elevations and areas of discharge. The discharge of groundwater may be through springs, into wells, or into wetlands or base flow of streams. In some areas where relatively impermeable beds or layers are present, groundwater may be confined within a more permeable bed, moving down-dip within the bed under artesian pressure.²²

The Conemaugh Group, which contains the Glenshaw Formation, is a productive water bearer in Somerset County. Several sandstone members may yield as much as 250 gpm and will usually supply ample quantities of water for domestic use.^{24,29} Of the 57 wells listed in the Groundwater Inventory System for Milford and Black Townships, 31 (about 54 percent) produce water from the Conemaugh Group. These wells range in depth from 37 to 439 feet, with a median depth of 123 feet. They have yields ranging from 1 to 30 gpm and have a median yield of 8 gpm. The median depth to groundwater is about 29 feet, and the median depth to consolidated bedrock is about 22 feet.²⁷

The Allegheny Group, which contains the Freeport, Kittanning, and Clarion Formations, is a good water bearer in places where it has not been dewatered by coal mining. Shales yield small supplies of water, and sandstones may yield 50 to 150 gpm.^{17,22} Of 57 wells listed in the Groundwater Inventory System for Milford and Black Townships, 23 (about 40 percent) produce water from the Allegheny Group. These wells range in depth from 46 to 204 feet, with a median depth of 96 feet. They have yields ranging from 0 to 55 gpm and a median yield of 10 gpm. The average depth to groundwater is about 43 feet, and the average depth to consolidated bedrock is about 23 feet.²⁷

TDD No.: F3-8910-16

The Pottsville Group can be a very productive water-bearing formation. It contains many artesian wells and some flowing wells. Some wells yield up to 100 to 400 gpm. Sandstones are the best producing members of the group.^{24,29} Only 1 of 57 wells listed in the Groundwater Inventory System for Milford and Black Townships produces from the Pottsville Group. This well is 104 feet deep and yields 10 gpm.²⁷

The Mauch Chunk Formation is capable of providing good yields of water locally where it is sandy and not too deeply buried. The limestone members of the formation may be good water producers where secondary permeability is developed by solution openings. Overall, the Mauch Chunk is generally unimportant as an aquifer in the area.^{24,29} No wells are listed in the Groundwater Inventory System for Milford and Black Townships, which produce from the Mauch Chunk Formation.²⁷

Three monitoring wells in the vicinity of the disposal pit on the site provide additional information concerning groundwater conditions at the site. Groundwater at the site occurs in the overburden and in the weathered bedrock. The depths of water inflow in the monitoring wells represent the intersection of the boreholes with either weathered rock intervals or fracture zones within these rocks. Water levels in the wells indicate a hydraulic gradient of the shallow groundwater to the east-southeast.⁹ At greater depths beneath the site, the regional groundwater flow may be to the northwest, following the general dip of the underlying rock strata.^{24,28}

The 3 on-site monitoring wells range in depth from 14 to 44 feet, with an average depth of 25.7 feet. Two of the wells yield less than five gpm. The third well yielded greater than 20 gpm when open to a depth of 44 feet and reportedly encountered flowing artesian conditions at 44 feet during drilling. After the depth was modified to 22 feet, this well yielded 2 to 3 gpm. The overburden thickness, or depth to bedrock, in the 3 wells ranges from 13.5 to 29 feet and averages 20.5 feet. The average depth to groundwater in the three wells ranges from 2.4 to 6.7 feet below the ground surface.⁹

There are more than five acres of wetlands within a three-mile radius of the site. These wetlands are hydraulically interconnected with the soils and shallow bedrock units that underlie them and serve as discharge points for groundwater.³¹

TDD No.: F3-8910-16

3.4 Climate and Meteorology

The Rockwood Compressor site is located in the Allegheny Plateau, which possesses a continental

type of climate with changeable temperatures and more frequent precipitation than other parts of

the state.³² The average annual temperature for Uniontown, Pennsylvania, located approximately 30

miles west of the site, is 52.2°F. The average annual precipitation is 40.29 inches.³³ The mean annual

lake evaporation is approximately 28 inches.³⁴ Therefore, the net annual precipitation is

approximately 12.29 inches per year. The 1-year, 24-hour rainfall is approximately 2.5 inches.³⁵

3.5 Land Use

The area surrounding the site is rural and is composed principally of open fields, farms, forests, and a

few residences. Many active and inactive underground coal mines, strip mines, and rock quarries are

also located throughout the region.¹⁷ State Game Lands No. 50 is located approximately 1.5 miles

north-northeast of the site.1

3.7 <u>Critical Environments</u>

According to the United States Department of the Interior, Fish and Wildlife Service, no known

endangered species reside within a three-mile radius of the site. However, two federally listed

endangered birds are expected to be found as transient species in the vicinity of the site. These

species are the bald eagle (Haliaeetus leucocephalus) and the peregrine falcon (Falco peregrinus).

There is no listed critical habitat for these species in the project area.³¹

There are no known wetlands within one mile of the site.³¹

3-9

TDD No.: F3-8910-16

3.4 Climate and Meteorology

The Rockwood Compressor site is located in the analysis and more frequent precipitation than other parts of the state.³² The average annual temperature for an annual precipitation is 40.29 inches.³³ The mean annual lake evaporation is approximately 28 inches.³⁴ Therefore, the net annual precipitation is approximately 12.29 inches per year. The 1-year, 24-hour rainfall is approximately 2.5 inches.³⁵

3.5 Land Use

The area surrounding the site is rural and is composed principally of open fields, farms, forests, and a few residences. Many active and inactive underground coal mines, strip mines, and rock quarries are also located throughout the region.¹⁷ State Game Lands No. 50 is located approximately 1.5 miles north-northeast of the site.¹

3.6 Population Distribution

The population estimated to live within a 1-mile radius of the site is 270 people; from 1 to 2 miles, the population is estimated to be 870 people, and from 2 to 3 miles, the population is estimated to be 948 people. Therefore, approximately 2,088 people live within a 3-mile radius of the site. These figures are based on a house count taken from the U.S.G.S. topographic quadrangles, multiplied by 3.8 people per house.¹

3.7 <u>Critical Environments</u>

According to the United States Department of the Interior, Fish and Wildlife Service, no known endangered species reside within a three-mile radius of the site. However, two federally listed endangered birds are expected to be found as transient species in the vicinity of the site. These species are the bald eagle (Haliaeetus leucocephalus) and the peregrine falcon (Falco peregrinus). There is no listed critical habitat for these species in the project area.³¹

There are no known wetlands within one mile of the site.31

ドラス

1

SECTION 4

TDD No.: F3-8910-16

4.0 WASTE TYPES AND QUANTITIES

Concern at the Rockwood Compressor Station involved the possibility of PCB contamination from an

unlined earthen disposal pit at the station site. Disposal pits at the compressor station along the

Texas Eastern Natural Gas pipeline were historically used for disposal of pipeline liquids removed

from the pipeline as a routine maintenance operation (see appendix B). In 1981, Texas Eastern

discovered PCB residues in the pipeline liquids. The source of the PCBs is attributed to contamination

of compressor-lubricating oil from residual PCB lubricating oil that was used from 1958 until 1977.⁷

Although, Texas Eastern claims to have never disposed PCB oils and/or PCB-contaminated pipeline

liquids at the Rockwood site, tests indicated some PCB contamination.6

As part of the 54-site screening initiated in June 1986, samples were collected at Rockwood. Analyses

of surface soil samples indicated 3.6 ppm PCBs, stream sediments contained 0.26 ppm PCBs, and a

drainage ditch sediment contained 0.97 ppm PCBs.37

Phase I surface soil and sediment sampling was conducted during November and December 1987.

Analysis of two off-site surface soil samples showed 1.4 and 1.8 ppm PCB, and two stream sediment

samples showed 24 and 38 ppm PCBs.¹⁷ On April 13, 1989, Weston conducted Phase II surface and

sediment sampling. Stream sediments contained PCB concentrations from 1.0 to 6.4 ppm; analysis of

on-site and off-site surface soils did not detect any PCBs.²⁰

Soil boring analysis also revealed PCB contamination. One boring was made outside of on-site pit,

and samples contained 2.0 to 2.1 ppm PCBs. Two borings inside the pit had samples containing 10 to

20 ppm PCBs. 19

The use of the Rockwood disposal pit by the federal government during the operation of the War

Emergency Pipeline during World War II is unknown. 13

4-1

SECTION 5

.

F3-8910-16

SEPA

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT AT 1 - SITE LOCATION AND INSPECTION INFORMATION

I. IDENTIFICATION
OF STATE OF STATE NAMED PA 2165

PART 1 - SITE LUCATION AND INSPECTION INFORMATION									
IL SITE NAME AND LOCA									
O1 SITE NAME (Logic common or opposition name or anni				02 STREET, ROUTE NO., OR SPECIFIC LOCATION IDENTIFIER					
Rockwood Compressor Station			Township Route 512						
03 CTY			04 STATE	05 ZP CODE	04 C	OUNTY	07COUNTY	2457	
Murdock			PA	15501	So	merset	111	12	
09 COOPENATES	L LONGITUDE .	T A CONNERSM			- .	STATE COLUMNY	- E LA (MC10	4	
390 56 18	APTILOR LONGITUDE . I.A. PRIVATE C. B. FEDERAL							_	
IIL INSPECTION INFORMATION									
01 DATE OF INSPECTION N/	A Z ACTIVE	03 YEARS OF OPERA							
WATER DAY FEAT	I NACTIVE		1940 s.	present		UNKNOWN			
JA AGENCY PERFORMING INS	PECTION (Chase as that easter)						·		
I A. EPA I B. EPAC	CHTRACTOR NUS COTE	oration	□ C. M	UNICIPAL G D. A	MUNIC	PAL CONTRACTOR			
I E. STATE I F STATE		AND OF PARTY	= G. 0	THER			*4000 or 4000		
05 CHIEF INSPECTOR		JOA TITLE			10	7 ORGANIZATION	JA TELEPHON	ENG.	
Decomposition .		Environment	al Sci	entist		NUS Corporation	1		
OR OTHER PASS SECTION		10 TITUE	u 1 JC1			1 ORGANIZATION	2 TELEPHON	MO.	
							1 ;		
					-+				
							1)		
					-+				
					_	i			
					- 1	!			
						į			
	and the second					<u> </u>			
13 SITE REPRESENTATIVES IN	TERVIEWED	14 ITLE		SACORESE			O TELEPHON	E NO	
						!			
			- 1				•		
			-						
				,					
			1				!		
							:		
							1		
		1					·		
							1		
									
				-					
17 ACCESS GAMED BY	18 THE OF HISPECTION	18 WEATHER COM	STICHE.						
N/A = PERMISSION	N/A	N /A							
= WARRANT	N/A	N/A							
IV. INFORMATION AVAI	LABLE FROM								
01 CONTACT		02 OF (Agenty Organ				-	TELEPOOR	0	
		US EPA				10			
04 PERSON RESPONSIBLE FO	OR SITE INSPECTION FORM	08 AGENCY	04 OR	GANIZATION	07	TELEPHONE NO.	CATE		
		AULE		т э		215) 607 0510	2/23/90)	
Jeffrey Miller		NUS	11	T 3	9	215) 687-9510	4,3174 4		

.. .

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT

L IDENTIFICATION OI STATE OZ SITE MAMBER

PART 3 - DESCRIPTION OF	HAZARDOUS CONDITIONS AND INC	IDENTS PA 2	165
HAZARDOUS CONDITIONS AND INCIDENTS COMME			
1 3 J. DAMAGE TO FLORA 4 NARRATIVE DESCRIPTION	02 C OBSERVED (DATE:	/ I POTENTIAL	I ALEGED
- Advantage DESCRIPTION			
None reported or observed.			
		• .	
1 G K. DAMAGE TO FAUNA 4 NARRATIVE DESCRIPTION (INC.)	02 C COSSERVED (DATE:	= POTENTIAL	I ALEGED
·			
None reported or observed.			
1 CONTAMINATION OF FOOD CHAIN 4 NARRATIVE DESCRIPTION	02 C OBSERVED (DATE:	? POTENTIAL	I ALEGED
None reported or observed.			
I M. UNSTABLE CONTAINMENT OF WASTES	02 C OBSERVED (DATE:	POTENTIAL	- ALEGEO
3 POPULATION POTENTIALLY AFFECTED: 270 / 1-mil			
Pipeline liquids containing PCBs and vo			
disposal pit on-site. Elevated levels o	of PCBS were found in an off-si	te drainage pathway	•
I O N. CAMAGE TO OFFSITE PROPERTY A NARRATIVE DESCRIPTION	02 C CBSERVED (DATE.	_ POTENTIAL	I ALEGED
a mounting best a right	•		
None reported or observed.			
1 CO. CONTAMINATION OF SEWERS, STORM DRAINS, WI	TPs 02 C OBSERVED (DATE.	_ C POTENTIAL	I ALLEGED
4 NARRATIVE DESCRIPTION			
None reported or observed.	•		
1 I P LLEGALIUNAUTHORIZED DUMPING	32 CBSERVED (DATE:	POTENTIAL	I ALLEGED
4 NARRATIVE DESCRIPTION			
None reported or observed.			
		•	
IS DESCRIPTION OF ANY OTHER KNOWN, POTENTIAL, OR A	LLEGED HAZAROS		
None reported on observed			
None reported or observed.			
	•		
L TOTAL POPULATION POTENTIALLY AFFECTED:	2088		
/. COMMENTS			
None.			
. SOURCES OF INFORMATION (Co. species responses, a. S. Han			
William P. On J. Co. J. Co.	144 644 8		A
William F. Graham, Soil Scientist Faci		_	
Chief, Program Evaluation, Bureau of W. NUS FIT 3. Site inspection, F3-8910-16	-	. september 25, 198	o/ .

		74
	-	
70		

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION

I. IDENTIFICATION							
OI STATE	02 SITE NUMBER						
DA	2165						

VUA	PART 4 - PERM	IT AND DESCRI	PTIVE INFORMA	TION	PA : 2165
II. PERMIT INFORMATION			T		
Chest of PERSON (SSLEE)	02 PERMIT MUMBER	OS CATE ISSUED	04 EXPERATION DAT	E 05 CCLARENTS	
I A. NPOES					
28. URC					
IC. AIR				-	
ID. RCRA					
CE. ACRA WITERM STATUS					
OF SPECPLAN					
□G. STATE.Seem					
IH LOCAL Seems					
II. OTHER /Seems				1.	
X.1. NONE					
SITE DESCRIPTION					
STORAGE DISPOSAL, Chair or the season	32 AMOUNT 33 UNIT (OF MEASURE 04 F	MEATABLET COME OF THE	-	35 OTHER '
C A. SURFACE IMPOUNDMENT		= ^	INCENERATION	None	X. A. BUILDINGS ON SIT
C 8.PLES			UNCERGROUND IN		A A BUILDINGS ON SI
I C. DRUMS, ABOVE GROUND			CHEMICALIPHYSIC		
II D. TANK ABOVE GROUND			BIOLOGICAL		3 34 AMEA OF SITE
I F LANGFILL			WASTE OIL PROCE SOLVENT RECOVE		SAME OF SILE
E G. LANDFARM			OTHER RECYCLIN		19
I H. OPEN DUMP			OTHER	anecoven t	
I OTHER unlined pit	unknown				
	?				
None					•,
	· · · · · · · · · · · · · · · · · · ·				
CONTAINMENT CONTAINMENT OF WASTES (Choss com					
Z A. ADEQUATE, SECURE	3 8. MODERATE	X C. NACEO	JATE, POOR	I D. INSECUI	RE UNSOUND, DANGEROUS
DESCRIPTION OF DRUMS, DRUMS, LINGING,	WATERE ETC.				
Sample analysis shows P	CBs in soil boring	s outside the	pit boundary	and in stre	ąm sediment.
ACCESSIBILITY					
OI WASTE EASELY ACCESSIBLE: 3 YES	Z NO				
PCBs were observed in s	tream sediment out	side the fen	ced site.		
COLLEGE OF INCOME.					
SOURCES OF INFORMATION (CO-4					

William F. Graham, Soil Scientist Facilities Section, Bureau of Waste Management to Bob Orwin, Chief, Program Evaluation, Bureau of Waste Management, Correspondence. September 25, 1987 NUS FIT 3. Site inspection. F3-8910-16. February 23, 1990.



POTENTIAL HAZARDOUS WASTE SITE

I. IDENTIFICATION

≎EPA		PART 5 - WATER	O1 STATE O2 SITE NUMBER PA 2165			
IL DRINKING WATE	SUPPLY					
OT TYPE OF OFFICE SU	PPLY		02 STATUS			. 33 CHETANCE TO SITE
	SURFACE	WELL	ENGANGERED	AFFECTED	MONITORED	
COMMUNITY	A. Ø	8. 🔾	A. 82	8. 🗆	c. 🗆	a. 750 feet mi
NON-COMMUNITY	c. 🗆	0. 🏗	0. 🛭	E. 🖸 F. 🗇		a. 750 feet
AL GROUNDWATER						
01 GROUNDWATER USE	N VICINITY (Clear or					
		C & OFFICERS	OUSTRIAL PRICATION	C COMMENCE	AL MOUSTRIAL MANG	ATION 3 O. NOT USED, UNUSEABL
OI GROUNOWATER USE	POR OFFINICING	C B. OPPOWERS OTHER SECTION COMMERCIAL, IN IND GREET WINEY SECTION		Laborate action of	and a second	ATION 30 NOTUSED UNUSEAR.
3 A. ONLY SOURCE	FOR OPENIONS BY GROUND WAT	C B. OPPOWERS OTHER SECTION COMMERCIAL, IN IND GREET WINEY SECTION	-	Laborate action of	REST DRUKING WATE	well 750 feet

10 RECHARGE AREA	11 DISCHARGE AR	•	
X YES COMMENTS Infiltration of precipitation	S YES COM	MMENTS Spring appro	ximately 150 feet
z wo on site.			pe from disposal pit.
	300	Tonicuso una dominara	pe Train exepted. pres
IV. SURFACE WATER .			
01 SURFACE WATER USE (Choose one)			
X A. RESERVOIR, RECREATION G. B. IRRIGATION, ECONOMICS IMPORTANT RESOURCES		MERCIAL INDUSTRIAL	2 0 NOT CURRENTLY USED
32 AFFECTED/POTENTIALLY AFFECTED BOOKS OF WATER			
YAME:		AFFECTED	DISTANCE TO SITE
Wilson Creek		_	1.2
Unnamed tributary to Wilson Creek			(101)
Official Co. 17 December 2011			imit
V. DEMOGRAPHIC AND PROPERTY INFORMATION			
01 TOTAL POPULATION WITHIN		02 DISTANCE TO NEAREST	POPULATION
ONE (1) MILE OF SITE TWO (2) MILES OF SITE THR	EE (3) MILES OF SITE		
A 270 A 1,140 C	2,088		.2
YO OF PERSONS YO, OF PERSONS	40. OF PERSONS		
03 NUMBER OF BUILDINGS WITHIN TWO (2) MILES OF SITE	04 DISTANCE TO	WEAREST OFF-SITE BUILDING	
300		2	
35 POPULATION WITHIN VICINITY OF SITE (Provide narrative economics of nature of providing			
The area surrounding the site is mostly rural,	composed of o	nen fields, farms	forests and scattered
	Composed of O	pen ricius, iuillis,	TOTOS UNA SCUCCETEU
residences.			

.Q.EDA

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT

I. IDENTIFICATION

PART 5 - WATER, DEMOGRAPHIC, AND ENVIRONMENTAL DATA PA 2165
VI. ENVIRONMENTAL INFORMATION
Of Office and the office of th
10-5-10-3 cm/sec 3 A 10-4-10-4 cm/sec 3 B. 10-4-10-4 cm/sec 3 C. 10-4-10-3 cm/sec 3 O. GREATER THAN 10-3 cm/sec
32 PERMEABLITY OF BEDROCK (Communication) 10 ⁻⁵ -10 ⁻³ cm/sec
A IMPERMEABLE 3 S. RELATIVELY IMPERMEABLE 3 C. RELATIVELY PERMEABLE 3 D. VERY PERMEABLE 3 C. RELATIVELY PERMEABLE 3 D. VERY PE
03 CEPTH TO BEDROCK 04 DEPTH OF CONTAMINATED SOIL ZONE 06 SOIL ON
36 NET PRECIPITATION 07 ONE YEAR 24 HOUR RAINFALL 08 SLOPE SITE SLOPE DIRECTION OF SITE SLOPE TERRAIN AVERAGE SLOPE
12.29 (n) 2.5 (n) 6 east to southeast 6
SITE IS IN N/A YEAR FLOODPLAN N/A N/A
11 OSTANCE TO CRITICAL HABITAT (or comment)
4.00
N/A OTHER N/A
A(mi) 9(mi) ENDANGERED SPECIES:
13 LAND USE IN VICINITY
OISTANCE TO:
RESIDENTIAL AREAS, NATIONAL/STATE PARKS, AGRICULTURAL LANCS COMMERCIAL/INDUSTRIAL FORESTS, OR WILDLIFE RESERVES PRIME AG LAND AG LAND
8. <u>< 1/4</u> (ms) C. N/A (ms) O. <u>< 1</u> (ms)
4 DESCRIPTION OF SITE IN RELATION TO SURROLLHOWN TOPOGRAPHY
The site is situated on an open hillside with a gentle eastward slope. Elevations in the vicinity of the site range from approximately 1,900 feet above mean sea level (MSL) at Coxes Creek less than one mile northwest of the site to approximately 2,260 feet above MSL at the crest of the hill south of the site. Relief on the site is about 60 feet, with the lowest point in the eastern corner (elevation 2,180 feet above MSL) and the highest point in the southern corner (elevation 2,240 feet above MSL).
VII. SOURCES OF INFORMATION -CIO appeals resources, a.g., many data, sample and their resources.

Roy F. Weston, Incorporated. Review and evaluation of the Phase I Groundwater Monitoring and

Assessment Program. Est. August 1988.

		EF	_	
L S	AM	PLES	TAK	Ε
s	M	LET	PE	
G	ACI.	MOW	ATER	

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT

L IDENTIFICATION							
O1 STATE	02 SITE NUMBER						
PA 2165							

	•	P	ART 6 - SAMPLE AND FIELD INFORMATION	<u> </u>	2100
L SAMPLES TA	KEN N/A				
SAMPLE TYPE		OI NUMBER OF SAMPLES TAKEN	02 SAMPLES SENT TO		OS ESTIMATED DATE PERLES AVALABLE
GROUNOWATE	A				
SURFACE WAT	er				·
WASTE					
AFR					
RUNOFF					
S PILL					
SOL					
VEGETATION				,	
OTHER					
IL FIELD MEAS	UREMENTS TA	KEN N/A			L
I TYPE		02 COLONENTS			
		;			
V. PHOTOGRAP	HS AND MAPS	3		······································	
31 TYPE X GRO	UNO C AERIAL		02 M CLISTOOV OF NUS FIT 3 and EPA files		
X YES	34 LOCATION				
2.80			nd NUS files		
V. OTHER FIELD	DATA COLLE	CTED (Annual control	N/A		
None					
None					•

VI. SOURCES OF INFORMATION (COM MINISTER F. S. AND THE LETTER STATES (THE PROPERTY OF THE PROP

NUS FIT. Site inspection. TDD No. F3-8910-16. February 23, 1990.

≎EPA	P	SITE INSP	CARDOUS WASTE SITE ECTION REPORT NER INFORMATION	N REPORT 01 STATE 102 SITE NUMBER		
IL CURRENT OWNERS			PARENT COMPANY			
O1 NAME	0	REDUKIN D+0 S	OS NAME	1	REDMANN 8+17 EC	
Texas Eastern Gas Pi	peline Company		Texas Eastern Transmi	ssion Corporat	on	
03 STREET ADDRESS (P Q am. APO F	-:	04 SEC CODE	10 STREET ADDRESS IP Q. Sec. AFO F. ex	L .	11 SIC CODE	
P.O. Box 2521			P.O. Box 2521			
06 CITY	OS STATES	7 ZP COOE	ISCUY	13 STATE	14 2P COOE	
Houston	TX	77252-2521	Houston	TX	77252-2521	
II NAME	o	2 D+6 NUMBER .	GB NAME		REGILLIN 8+0 60	
DI STREET ADDRESS (P. D. am. APD P. o		04 SIC COOE	10 STREET ACCRESS IP Q. DOL. NPD P. and	<u> </u>	11 SC CODE	
04 CITY	OS STATE	17 2P COOE	12 017	13 STATE	14 EP CODE	
01 NAME		02 0+6 MUMBER	OS MAME		REDMUM D+0 00	
03 STREET ADDRESS IP C. Sec. MO F.		04 SIC CODE	10 STREET ACCRESS IP G and APP	l.	115C COOE	
06 CITY	OS STATE	or opene	12 GTY	13 STATE	14 29 COOE	
DI NAME		DZ D+6 MINABER	OS MANIE	1	REBILLIN B+080	
03 STREET ACCRESSIO Q am MOO.	1	04 SIC CODE	10 STREET ACCRESS IP G and APO P and		I I SIC CODE	
05 CITY	GS STATE O	OF COOR	12 GTY	13 STATE	14 2P CODE	
IIL PREVIOUS OWNERSS.			IV. REALTY OWNERS)	: 00 AND AND		
OI NAME		20+6 MUNICER	O1 MANE		RED+6 NUMBER	
U.S. Government			N/A	İ		
OJ STREET ADDRESS IP O. am. APG &	4. /	34 SIC COOE	03 STREET ACCRESSIO O. Ann. APO F an		04 EIC CODE	
05 CITY	OSTATE O	7 ZP CODE	osarv	OG STATE	OF DP COOE	
OI NAME		20+6 MUMBER	O1 NAMS		02 D+0 NUMBER	
N/A			N/A			
03 STREET ADDRESS IP 0. am. APP.		04 SIC CODE	03 STREET ACCRESS IP G. III. APP.	u	04 SIC COOL	
OS CITY	OS STATE O	7 ZP COOS	OS CITY	OB STATE	7 ZP COOE	

William F. Graham, Soil Scientist Facilities Section, Bureau of Waste Management to Bob Orwin, Chief, Program Evaluation, Bureau of Waste Management, Correspondence. September 25, 1987 NUS FIT 3. Site inspection. F3-8910-16. February 23, 1990.

04 SIC COOK

OBSTATE OF ZP COOK

N/A

05 CITY

03 STREET ACCRESSIO Q AM APO

02 D+6 NUMBER

OS STATE OF ZIP COOS

04 SIC CODE

01 NAME

osary

N/A

OS STREET ACOMESSIP O. BEL APP.

Y. SOURCES OF INFORMATION (Chie

ŞEPA

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT PART 8 - OPERATOR INFORMATION

į	I. IDENTIFICATION							
	01	STATE	02 SITE NUMBER					
		PA	2165					

IL CURRENT OPERAT	OR			OPERATOR'S PARENT COMPANY / MARRIAGON				
01 NAME			02 D+6 NUMBER	10 NAME 11 0+6 NU		1 0+6 NUMBER		
Texas Eastern G	as Pipeline Co	mpany		Texas Eastern Trans	mission Corporati	on		
03 STREET ADDRESS IP.Q.		, ,	04 SEC CODE	12 STREET ADDRESS (P.O. Sec. APO	13 SIC COOE			
P.O. Box 2521			}	P.O. Box 2521				
OA CITY		OS STATE	07 ZP COOS	114 GTY	15 STATE	16 ZP COOE		
Houston		ТХ	77252-2521	Houston	TX	77252-2521		
OR YEARS OF OPERATION	OR NAME OF OWNER							
1940s-Present		ern Gas	Pipeline Comp	pa n y				
IIL PREVIOUS OPERA	TOR(S)	~	· · · · · · · · · · · · · · · · · · ·	PREVIOUS OPERATORS' P	ARENT COMPANIES			
01 NAME			02 D+6 NUMBER	10 NAME		11 0+8 NUMBER		
U.S. Government	;			N/A				
03 STREET ADDRESS IP Q	Sec. AFO F. 100.1		04 SIC COOE	12 STREET ADDRESS IP O. But. APE	9 e. ess.1	13 SIC CCOE		
						•		
06 CITY		OS STATE	07 ZP COOK	14017	15 STATE	16 2P COOE		
OS YEARS OF OPERATION	OR NAME OF OWNER	CLIPTOR'S THE	PERIOD					
1940s	J		02 D+6 MUMBER	10 NAME		1 ! O+d NUMBER		
U1 MARKE			UZ U T B MUNINEM	10 100		1: U+ 6 NUMBER		
03 STREET ADDRESS (P. Q. &	ME. APD 4 ME.		04 SIC COOE	12 STREET ADDRESS IP 0. Sec. APO) # eq. ;	13 SIC CODE		
05 CITY		CB STATE	07 ZP CODE	34 CITY	15 STATE	18 ZIP CODE		
GE YEARS OF OPERATION	DO MANE OF OWNER	OUPMA THE	S PERIOD					
	İ			1		4.		
01 NAME			02 C+6 NUMBER	10 NAME		11 J+8 NUMBER		
		1						
03 STREET ADDRESS (P.O. A	N. 450.0 mm.		04 SIC CODE	12 STREET ACCRESS (P.O. Box. AFC	10 000	113 SIC CODE		
						ļ		
QS CITY		OR STATE!	07 ZP COOR	14 CITY	i s crivel	16 ZP CODE		
OB SIXIE OF			1	ISSIAIE	10 AP COUR			
20 10 100 00 0000 1	T							
OB YEARS OF OPERATION	08 NAME OF OWNER	DUFFIG THE	PERIOD					
IV COURCES OF INC	DOM A TION							

William F. Graham, Soil Scientist Facilities Section, Bureau of Waste Management to Bob Orwin, Chief, Program Evaluation, Bureau of Waste Management, Correspondence. September 25, 1987.

NUS FIT 3. Site Inspection. F3-8910-16. February 23, 1990.

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT PART 9 - GENERATOR/TRANSPORTER INFORMATION

LIDE	ITIFICATION
O1 STAT	E 02 SITE NUMBER
PA	2165

NAME	10	2 0+6 NUMBER			
exas Fastern Gas Pipe	line Company	04 SIC CODE	-		
			_		
.0. Box 2521	OS STATE	07 ZP COOK	-		
ouston	тх	77252-2521			
L OFF-SITE GENERATORIS					
1 NAME		2 D+0 NUMBER	01 NAME	02	D+6 NUMBER
/A					
STREET ADDRESS IP O AM. APOP	erE.)	04 SIC CODE	03 STREET ADDRESS IP O. Ban. APC) # est.;	34 SIC COO
5 CITY	06 STATE	7 25 COO€	06 CITY	CA STATE OF	UP CODE
				· ·	
1 NAME		2 D+6 MUMBER	OI MANE	0:	D+6 MUMBER
				1	
03 STREET ADDRESS IP O. MA. APO . W.		04 SIC CODE	03 STREET ADDRESS (P O. dec. AM) e est.;	04 SIC COO
					İ
6 arv	OSTATE DO	7 ZP COOE	OS CITY	OSTATE OF	The COOR
/. TRANSPORTER(S)					
NAME		2 D+6 NUMBER	OI MAME	02	0-8 NUMBER
1/A	?			i	
STREET ADDRESS (P.O. Am. AFO.		04 SIC CODE	03 STREET ADDRESS (P.O. Bac. MO	· ·	34 SIC COO
					!
sary	OG STATE	7 2P COOE	06 CITY	OS STATE OF	2000E
1 NAME	l°	2 D+8 NUMBER	JI NAME		S-4 MUMBER
STREET ADDRESS (P.O. ann. MO.	een.j	04 SIC CODE	03 STREET ADDRESS IP 0. Bas. APC) ≠ emp. ;	34 SIC COOE
SCITY	OG STATE!	17 700 COOK	05 CITY	OS STATE OF	3P C2006

NUS FIT 3. Site Inspection. F3-8910-16, February 23, 1990.

ŞEPA

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT

DENTIFICATION
O1 STATE 02 SITE NAMES
PA 2165

	PART 10 - PAST RES	PONSE ACTIVITIES	1A 2103
IL PAST RESPONSE ACTIVITIES			
31 C A. WATER SUPPLY CLOSED	02 DA	TE 33 AGENCY	
34 DESCRIPTION			
N/A			
01 (3 B. TEMPORARY WATER SUPPLY 04 DESCRIPTION	PROVIDED 02 DA	TE 33 AGENCY	
N/A			
01 C. PERMANENT WATER SUPPLY 04 DESCRIPTION	PROVIDED 02 DA	TE 03 AGENCY	
N/A		ITE 33 AGENCY	
01 C 0. SPILLED MATERIAL REMOVED 04 DESCRIPTION	J2 DA	18	
N/A			
J1 C E. CONTAMINATED SOIL REMOVE 34 DESCRIPTION	5D 32 DA	TE 03 AGENCY	
N/A			•
01 C F WASTE REPACKAGED	02 DA	TE 03 AGENCY	
04 DESCRIPTION			
N/A O1 C G. WASTE DISPOSED ELSEWHER	S 02 DA	ATE 03 AGENCY	
04 DESCRIPTION			
N/A		20.05.00	
01 Z H. ON SITE BURIAL 04 DESCRIPTION	02 DA	TE 33 AGENCY	
N/A			
01 C I. IN SITU CHEMICAL TREATMENT	02 DA	TE 03 AGENCY	
N/A 01 G J. IN SITU BIOLOGICAL TREATME	MT 02.04	TE 33 AGENCY	
04 DESCRIPTION	V2 54		
N/A		ITE 33 AGENCY	
01 (2 K. :N SITU PHYSICAL TREATMENT 04 DESCRIPTION	F 32 DA	IE SAGENCY	
N/A			
01 3 L ENCAPSULATION 04 DESCRIPTION	02 DA	TE 03 AGENCY	
N/A			
01 (M. EMERGENCY WASTE TREATM 04 DESCRIPTION	ENT 02 DA	TE 33 AGENCY	
N/A			
31 G N. CUTOFF WALLS 04 DESCRIPTION	02 DA	TE 33 AGENCY	
N/A			
31 C O. EMERGENCY DIKING/SURFACE	E WATER DIVERSION 02 DA	TE 03 AGENCY	
04 DESCRIPTION N/A			
J1 C P CUTOFF TRENCHES/SUMP	02 DA	ITE 03 AGENCY	
34 DESCRIPTION	•••		
N/A			
31 G. SUBSURFACE CUTOFF WALL. 04 DESCRIPTION	02 DA	TE 03 AGENCY	
N/A			

SEPA

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT PART 10 - PAST RESPONSE ACTIVITIES

		DENTIFICATION					
ĺ	01	STATE	02 SITE NUMBER				
ı		PA	2165				

47 La. 7 (PART 10 - PAST RESPONSE ACTIVITIES	
II PAST RESPONSE ACTIVITIES		
31 C R. BARRIER WALLS CONSTRUCTED 34 DESCRIPTION N/A	02 DATE	OJ AGENCY
31 G. S. CAPPING/COVERING 04 DESCRIPTION N/A	02 DATE	33 AGENCY
01 C T. BULK TANKAGE REPARED 04 OESCRIPTION N/A	G2 DATE	OS AGENCY
31 Z U GROUT CURTAIN CONSTRUCTED 34 DESCRIPTION N/A	02 DATE	OJ AGENCY
01 TV BOTTOM SEALED 04 DESCRIPTION N/A	02 DATE	OJ AGENCY
01 G W GAS CONTROL 04 DESCRIPTION N/A	02 DATE	CI AGENCY
31 C X. FRE CONTROL. 04 DESCRIPTION	02 DATE	03 AGENCY
N/A 01 G Y LEACHATE TREATMENT 04 DESCRIPTION	02 DATE	O3 AGENCY
04 DESCRIPTION	OZ DATE	OJ AGENCY
N/A 31 3 1 ACCESS TO SITE RESTRICTED 34 DESCRIPTION N/A	02 DATE	03 AGENCY
31 T 2. POPULATION RELOCATED 34 DESCRIPTION	UZ DATE	OJ AGENCY
N/A 01 C 3. OTHER REMEDIAL ACTIVITIES 04 DESCRIPTION	02 DATE	O3 AGENCY
N/A		٠.

III. SOURCES OF INFORMATION COMMENTATIONS, S.C. AND SEE ASSESSED AND ASSESSED.

NUS FIT 3. Site Inspection. F3-8910-16, February 23, 1990.



POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT PART 11 - ENFORCEMENT INFORMATION

L IDENTIFICATION
OI STATE OZ SITE NUMBER
PA 2165

IL ENFORCEMENT INFORMATION

OI PAST REGULATORY/ENFORCEMENT ACTION X2 YES 3 NO

02 DESCRIPTION OF FEDERAL STATE LOCAL REGULATORY/ENFORCEMENT ACTION

Texas Eastern entered into a Consent Order with PA DER, on April 1, 1987 that established a comprehensive phased program to assess environmental conditions at and around the 18 station sites along the Texas Eastern pipeline in Pennsylvania.

On March 15, 1988, PA DER issued to Texas Eastern a unilateral administrative order for disposal area assessment and remediation. This order required Texas Eastern to investigate, characterize, and remediate any additional pits and other areas identified by Texas Eastern not addressed by the April 1, 1987 Consent Order.

IIL SOURCES OF INFORMATION CAN ASSESS (SECTION ASSESSED AND ASSESSED ASSESSED ASSESSED ASSESSED ASSESSED ASSESSED ASSESSED ASSESSED ASSESSED ASSESSED ASSESSED ASSESSED ASSESSED ASSESSED ASSESSED ASSESSED ASSESSED ASSESSED

Texas Eastern Gas Pipeline Company. Detailed Plan for the Investigation and Characterization identified areas at Texas Eastern's Pennsylvania sites. May 16, 1988.

NUS FIT 3. Site Inspection. F3-8910-16, February 23, 1990.

ŞEPA

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT

LIDENTIFICATION .						
OI STATE	02 SITE NUMBER					
PA	2165					

PART 2 - WASTE INFORMATION								
IL WASTE ST	ATES, QUANTITIES, AN							
OI PHYSICAL	TATES (Cheer of the state)	DZ WASTE QUANT	TY AT SITE			PRETICS (Cheer of the sta		
X A. SOLLO	J E. SLUMY	TONS		X A TOXIC JE SOLUBLE JI HIGHLY VOLATILE Z A COMPOSIVE JE HIGHTUS J. EXPLOSIVE				
C C. SLUGGE				~		STITE _ L PURE		Æ.
C D. OTHER		CUEIC YAROS .	unknown	X 0. A		- 3 M. KSM1A	S M. NOT AP	
	Spently	NO. OF DPLANS	· · · · · · · · · · · · · · · · · · ·					
IL WASTET	YPE							
CATEGORY	SUBSTANCE N	AME	OT GROSS AMOUNT	02 UNIT OF MEA	SUME	03 COMMENTS		
SLU	SLUDGE					-		
OLW	OLY WASTE "							
SOL	SOLVENTS							
250	PESTICIDES							
၁၀င	OTHER ORGANIC CH	EMICALS	unknown			PCBs associat	ted with mainte	nance
⊙ c	NORGANIC CHEMIC	ALS					ay have been di	
4C0	ACIOS						e pit or spille	
3AS	BASES					surface soils		
₩ES	HEAVY METALS							
IV. HAZARDI	OUS SUBSTANCES		r case CAE Partiers					
01 CATEGORY	02 SUBSTANCE N	AME	03 CAS NUMBER	04 STORAG	4/04/	OSAL METHOD	05 CONCENTRATION	ONCENTRATION
SOL	polychlorinated b	iphenyls	12672-29-6	disposal	oit		38.0	ppm
SOL	butanone		78-93-3	disposal	oit		12.0	ppm
SOL	styrene		100-42-5	disposal	pit		1.7	ppm
S01	2-methylnaphthale	ene .	91-57-6	disposal	pit		3.8	ppm
SOL	naphthalene		91-20-3	disposal	oit		6.0	ppm
							٤	
						i		
V. FEEDSTD	CXS (See Assessed for CAS Manage		N/A	L				
CATEGORY			02 CAS NUMBER	CATEGORY		OI FEEDSTO	CK NAME	J2 CAS NUMBER
FOS	***************************************			FOS	-			
F03				FOS	\dashv			
FOS				FOS	+			
F0 S				F03	-			
	S OF INFORMATION ICH				!			
Journe	OF INFORMATION (Ch							
William	F. Graham, Soil S	Scientist Fa	cilities Secti	on, Bureau	of	Waste Manageme	ent to Bob Orwi	n.

William F. Graham, Soil Scientist Facilities Section, Bureau of Waste Management to Bob Orwin, Chief, Program Evaluation, Bureau of Waste Management, Correspondence. September 25, 1987 NUS FIT 3. Site inspection. F3-8910-16. February 23, 1990.

SEDA

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT

L	:DENT	TP	CAT	TON
01	STATE	02	SITE	MAMMER
	PA		216	5

PART 3 - DESCRIPTION OF H	AZARDOUS CONDITIONS AND INCIDENT	S LPA	2105
L HAZARDOUS CONDITIONS AND INCIDENTS			
PCBs detected in on-site pit boring could revealed the presence of PCBs at 10 to 24			
compounds.			
01 C. B. SURFACE WATER CONTAMINATION 20 POPULATION POTENTIALLY AFFECTED: 2088	02 C CASERVED (DATE:; 04 NARRATIVE DESCRIPTION	X POTENTIAL	C ALEGED
PCBs from possible waste dumping into di to 38 ppm.	sposal pit have contaminated strea	m sediment at	levels up
31 T.C. CONTAMINATION OF AIR 33 POPULATION POTENTIALLY AFFECTED:	02 C OBSERVEDIDATE:	2 POTENTIAL	I ALLEGED
None reported or observed.			-
01 T. D. FREIEVELOSIVE CONDITIONS 03 POPULATION POTENTIALLY AFFECTED:	02 C OBSERVED (DATE	I POTENTIAL	I ALEGED
None reported or observed.		•	
DI DE CONTACT DI POPULATION POTENTIALLY AFFECTED: 270/1mile 04 NARRATIVE DESCRIPTION PCBs from possible waste dumping into a disposal pit or on the soil have been detected outside			
the fenced site in stream sediment at lev	els up to 38 ppm.		<i>'</i> :
31 XF CONTAMINATION OF SOIL 33 AREA POTENTIALLY AFFECTED: 49	02 C OBSERVED (DATE; 04 NARRATIVE DESCRIPTION	Ž POTENTIAL	I ALEGED
Low concentrations of PCBs, butanone, styrene, 2-methylnaphthalene, and naphthalene have been detected in soil boring and stream sediment samples.			
	*		
31 S.H. MORKER EXPOSURE/INJURY 33 WORKERS POTENTIALLY AFFECTED:	02 C OBSERVED (DATE:	S POTENTIAL	CALEGED
None reported or observed.			
31 C. POPULATION EXPOSURE/INJURY 33 POPULATION POTENTIALLY AFFECTED: None reported or observed.	02 C OBSERVED (DATE:; 04 NARRATIVE DESCRIPTION	C POTENTIAL	I ALEGED
none reported or observed.			

SECTION 6

TDD No.: <u>F3-8910-16</u>

6.0 REFERENCES FOR SECTIONS 1.0 THROUGH 5.0

United States Geological Survey. Murdock, Pennsylvania Quadrangle, 7.5 Minute Series.
 <u>Topographic Map.</u> 1968, photorevised 1981. Combined with Rockwood, Pennsylvania Quadrangle, 7.5 Minute Series. <u>Topographic Map.</u> 1968, photorevised 1981.

- 2. NUS Corporation. Review of Texas Eastern Compressor Stations in Pennsylvania. TDD No. F3-8702-19, March 9, 1987.
- 3. William Shawley, Bureau of Solid Waste Management. Narrative Summary. June 16, 1987.
- 4. Roy F. Weston. Groundwater Assessment and Monitoring Work Plan. March 1987.
- Roy F. Weston. Pit Cleanup Program for the Pennsylvania Sites. January 28, 1988.
- Manges, Eric, Hydrogeologist, Bureau of Waste Management, to A.D. Orlando, Chief,
 Operations Section. Correspondence. December 7, 1987.
- 7. Kirby, Calvin L. III, Solid Waste Specialist, Pennsylvania Department of Environmental Resources, Harrisburg Region. Preliminary Assessment of Texas Eastern Pipeline Company, Chambersburg Station No. 23. March 6, 1987
- 8. Texas Eastern Gas Pipeline Company. Detailed Plan for the Investigation and Characterization of Identified Areas at Texas Eastern's Pennsylvania Sites. May 16, 1988.
- 9. Roy F. Weston. Review and Evaluation of Phase I Groundwater Monitoring and Assessment Program. Undated.
- Pennsylvania Department of Environmental Resources. Texas Eastern Pipeline Company.
 Update. March 14, 1988.
- Subcommittee on Superfund and Environmental Oversight. Report Concerning the Performance of the Environmental Protection Agency in the Matter of the Texas Eastern Gas Pipeline Company. February 1988.

APPENDIX A

-

.

TDD No.: <u>F3-8910-16</u>

34. United States Department of Commerce. <u>Climatic Atlas of the United States</u>. Mean Annual Lake Evaporation. National Climatic Center, Asheville North Caroline. 1979.

- 35. United States Department of Commerce. <u>Climatic Atlas of the United States</u>. One-Year, 24-Hour Rainfall. National Climatic Center, Asheville, North Carolina. 1979.
- 36. Perry Edward W., Active Supervisor, United States Department of the Interior, Fish and Wildlife Service, to Garth Glenn, NUS FIT 3. Correspondence. November 13,1989.
- 37. Roy F. Weston, Incorporated. Preliminary Report of Sampling Program at Texas Eastern Company Site. December 1986.

TDD No.: <u>F3-8910-16</u>

24. Flint, Norman K., Pennsylvania Department of Environmental Resources, Bureau of Topographic and Geologic Survey. Geology and Mineral Resources of Southern Somerset County, Pennsylvania. County Report 56A, 1965.

- 25. United States Geological Survey. Markleton, Pennsylvania Quadrangle, 7.5 Minute Series.

 <u>Topographic Map.</u> 1968, photorevised 1973.
- 26. United States Geological Survey. Bakersville, Pennsylvania Quadrangle, 7.5 Minute Series. Topographic Map. 1967, photorevised 1973.
- 27. Pennsylvania Department of Environmental Resources, Bureau of Topographic and Geologic Survey. Groundwater Inventory System of Somerset County. May 1984.
- 28. Manges, Eric T., Hydrogeologist, Bureau of Waste Management, Southwestern Regional Office, to Terry R. Fabian, Regional Environmental Protection Director, Southwestern Regional Office. Correspondence. March 6, 1987.
- Lohman, Stanley W., Pennsylvania Department of Environmental Resources, Bureau of Topographic and Geologic Survey. Groundwater in South-Central Pennsylvania. Water Resource Report 5, 1938.
- 30. United States Department of Agriculture, Soil Conservation Service. <u>Soil Survey of Somerset</u> County, Pennsylvania. 1983.
- 31. United States Department of the Interior, Fish and Wildlife Service. Murdock, Pennsylvania Quadrangle. National Wetlands Inventory. April 1982. Combined with Rockwood, Pennsylvania Quadrangle. National Wetlands Inventory. April 1982.
- National Oceanic and Atmospheric Administration. <u>Climatography of the United States</u>. No. 60, Climate of Pennsylvania. National Climatic Center, Asheville, North Carolina. Reprinted, June 1982.
- National Oceanic and Atmospheric Administration. <u>Climatography of the United States</u>. No.
 Climate of Pennsylvania. National Climatic Center, Asheville, North Carolina. 1951 until
 Reprinted June 1982.